



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT
Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	Street Name	Significant Landmark
W0522, W0526, W0461, W0459, W0437, W0445	NA, Shetty Lyt, 2nd Main Rd, Shetty Lyt, 4th Main Rd	Shivanahalli main and cross roads
Segment No.	Total Length (m)	
1/C-W0522/S101418	232.78	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	191.04	77.600423	13.092579	77.600720	13.090894	W0522	W0461
2	41.74	77.601209	13.092015	77.600825	13.091983	RI-S52	W0465

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Asphalting and Improvements to Roads at Shivanahalli main and cross roads in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	4000000	2017
Year	Type of Work	Other Work Type
2017 - 2018	Asphalting	
Tender	Work Details	Job No. / Work Code
Not a Tender	Asphalting and Improvements to Roads at Shivanahalli main and cross roads in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	001-17-000038
Work Order No.	Work Order Date	Period of Extention
BBMP/EE (YNK D) /WO/134/2017 -18	31/03/2017	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
30/04/2017	29/04/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	E-Mail ID	
9449863065		

Zone: YELAHANKA

Ward No: 1

Ward Name: Kempegowda Ward

Street ID: W0522,
W0526,
W0461,
W0459,
W0445

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Field Inspection Details

Number of Trees

4

Any Other Information

Name

SACHIN

Date of Inspection

13/05/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Road Condition		This photo seems out of range

Zone: YELAHANKA

Ward No: 1

Ward Name: Kempegowda Ward

Street ID: W0522,
W0526,
W0461,
W0459.

Asst. Executive Engineer
Yelahanka Sub. Division
(P. & T. Ynk. Zn)
Yelahanka, Bangalore

[Handwritten signature]

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.


Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	13/05/2017	12/06/2017	COMPLETED
SE	VASU K M	13/05/2017	12/06/2017	COMPLETED
EE	VASU K M	13/05/2017	12/06/2017	COMPLETED
AEE	DEVARAJ	13/05/2017	12/06/2017	COMPLETED
AE	SACHIN	13/05/2017	12/06/2017	COMPLETED
AE	SACHIN	13/05/2017	12/06/2017	COMPLETED

Zone: YELAHANKA

Ward No: 1

Ward Name: Kempegowda Ward

Street ID: W0522,
W0526,
W0461,
W0459,
W0458, 111



Ass. Engineer
Yelahanka Sub. Div.
(BBMP Ynk. Zn)
Yelahanka, Bangalore